

MARYLAND VEHICLE INSPECTION REPORT

Initial Inspection Date: 09/14/2016

Station Name: [REDACTED]

Result: FAIL

Inspector: [REDACTED]

Vehicle: 1994 BMW K75

Initial Odometer: 175323

Station Number: [REDACTED]

VIN: [REDACTED]

Ending Odometer: n/a

Work Order Number: [REDACTED]

Customer Name: [REDACTED]

Vehicle Class: M

Phone: [REDACTED]

Cert. #: [REDACTED]

Cert. Date: [REDACTED]

Address: [REDACTED]

ROAD TEST

	P	F	R
Service Brake Performance:	X		

EXHAUST SYSTEM

	P	F	R
Muffler:	X		
Any Piping:	X		

FRAME

	P	F	R
Frame Condition:	X		

STEERING

	P	F	R
Swing Arm:	X		
Steering Head:	X		
Handle Bars:	X		

LIGHTING

	P	F	R
Turn Signals:	X		
Back Up:	N/A	N/A	N/A
Hazard:	X		
Indicator Lamps:	X		
Stop:	X		
Tail:	X		
Park:	N/A	N/A	N/A
Side Marker:	X		
Reflectors:	X		
Tag:	X		
Dash:	X		
Headlamps:	X		
Fog/AUX Height/Aim:	N/A	N/A	N/A

BODY

	P	F	R
Side/Center Stand:	X		
Chain Adjustment:	X		
Chain Guard:	X		
Seat:	X		

ALIGNMENT

	P	F	R
Wheel Alignment:	X		

PASSENGER ITEMS

	P	F	R
Hand Hold:	X		
Foot Rest:	X		

SUSPENSION

	P	F	R
Wheel Bearings:	X		
Shock Absorbers:	X		

FENDERS

	P	F	R
Fenders:	X		

ELECTRICAL SYSTEM

	P	F	R
Horn:		X	
Switches/Wiring:	X		
Connections:	X		

ADDITIONAL COMMENTS

BRAKES

	P	F	R
Hydraulic System:	X		
Drums/Discs:		X	
Lining/Pads:	X		
Mechanical Components:	X		
Mechanical Linkage:	X		
Drums/Discs - Front Spec:	.140		
Drums/Discs - Front Reading:	.136		
Drums/Discs - Rear Spec:	tamped no		
Drums/Discs - Rear Reading:	.103		
Lining/Pads - Front:	3/32		
Lining/Pads - Rear:	4/32		

left front rotor below spec rear rotor not stamped
w spec

SPEEDOMETER/ODOMETER

	P	F	R
Speedometer:	X		
Odometer:	X		

GLAZING

	P	F	R
Windshield or Windscreen:	X		

MIRRORS

	P	F	R
Left/ Right:	X		

EMISSIONS

	P	F	R
Catalytic Converter:	N/A	N/A	N/A
Fuel Filler:	X		
Positive Crankcase:	N/A	N/A	N/A
Air Injection:	N/A	N/A	N/A
Gas Recirculation:	N/A	N/A	N/A
Evaporative Emissions:	N/A	N/A	N/A

WHEELS AND TIRES

	P	F	R
Front:	X		
Rear:	X		