

Wiring diagram – late K100 RS and RT models