

# Service-Information Motorcycle



©BMW of N.A.  
Service Department

Group: 11  
ENGINE

APRIL 1993  
11 055 93  
(2583)

For USA Only

## COOLANT OVERFLOW TANK K MODELS

### INFORMATION:

The overflow line which previously was routed from the radiator filler neck to the front of the overflow tank (just below the sight tube), has been modified and now is routed to a nipple at the rear of the overflow tank.

### REASON FOR CHANGE:

To allow extra room for wiring and hoses between the frame tube and coolant tank. The tank was modified.

### EXTRA PART REQUIRED:

Due to the change in position of the nipple on the overflow tank, a longer hose is needed by ordering part number 17 11 1 152 866. You will receive one meter of hose which is sufficient to reach from the radiator filler neck to the overflow tank.

Very truly yours,

BMW of North America, Inc.

Joe Wagner  
National Service Manager  
Motorcycle Group

Richard Dampf  
National Technical Manager

JW/kf/499

Please initial and route to the following before filing				
Service	Parts	Sales	Warranty	Technicians